








Note: All material & labor furnished by Tyson Co.



Bench Marks -
S.W. Corner Conc. Service Walk Hse. #560
Pennock Ave. S.W. Elev. 127.18
Hyd. N.E. Corner 6TH & Oberlin Ave. S.W.
Elev. 133.11



TYSON ROLLER BEARING CO. **STORM SEWER**

Laterals from Pennock Ave. S.W.
Constructed Oct. 1942 by Tyson Co. - P.E. Bickel
Contractor - Rice & Wallace - Constr. Engrs. - J. Ehmer
Inspector - Plotted 12-15-42 by H. Piper
Constr. Notes - N.B. 158 - P. 74-75 Final Notes - N.B. 161 - P. 25

