Nº 10405

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-15-94	IF SO HOW AND LOCATION FROM 223 FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2323	THIS MARTICLE DOWN OFFICE AND ADDRESS OF THE PROPERTY OF THE P	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN YR 5	NAME OF CONTRACTOR 5 harrison Eff	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
J.W	725' V2'8" DEEP W/ CLEAN OUT	
SIGNED Bill Pan Inspector for City	THE AT ENGINEER'S OFFICE	
Hishermi Introffs		
REMARKS		

Nº 10405 fap	OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER
	MASSILLON, OHIO, Sep 7
RECEIVED OF	MASSILLON, OHIO, DEP 1 ANNOM'S EXC. FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Loane
TO TAP San	SEWER ON THE South
of Nave Rd S	SE AVE.
THE PREMISES BEING LOT NO	0L564 , HOUSE NO. 2323
WORK TO BE DONE IN ACCORDANCE OF THE DEPARTMENT OF PUBLIC SER	WITH Section 29 WITH Codified Ordinances South of Technology

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.