## Nº 11083

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 6/0  SIZE OF PIPE USED 6	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB? 435	NAME OF CONTRACTOR Manita Edc.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
RicoP	22 15- 105EP	
SIGNED Inspention for City	FILED AT ENGINEER'S OFFICE	

Nº 11083

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

·	MASSILLON, OHIO,	June 20,20_		
RECEIVED OFMahuite	Excavating	FEE OF \$		
	alavite			
REPAIR	•	4		
CUTOFF-				
OF (A) (A) (A) ST. TYPE	OF STREET	s phatr		
THE PREMISES BEING LOT NO	, HOUSE NO	<u>610                                    </u>		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR Malauric	,			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.