N^{0} $1\overline{1}55\overline{9}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM
HOUSE NO2595	FIRST MANHOLE DOWN STREAMOO
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED. 2595 Madone 7'dp F7' 40'- 222 11'dp -24'
SIGNED Inspector for City REMARKS	FILED AT ENGINEER'S OFFICE

Nº 11559

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,	<u>έσ')</u>
RECEIVED OF MALAULT FEE OF \$	ے۔
FOR WHICH PERMISSION IS GRANTED	······································
REPAIR SEWER ON THE CAST	S
CUTOFF OF MANAGE ST. TYPE OF STREET ACTION ACTIO	
THE PREMISES BEING LOT NO. 4191	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF	THE
DEPARTMENT OF PUBLIC SERVICE.	1111C
NAME OF CONTRACTOR TO THE ASSESSMENT AND ALLEY	(* gar

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.