№ 11698

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4/16/03	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAINYes	NAME OF CONTRACTORShetler
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED. 4590 BrightLeaf Ave Nw 457 457
SIGNED BIT Pappa 5 Inspector for City	FILED AT ENGINEER'S OFFICE
DEMARKS	

Nº 11698

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	V/.207
RECEIVED OF Atti	The second of th	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
of Michiel Cul Styl	EWER ON THE	Lact 4540
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. DEPARTMENT OF PUBLIC SERVICE.	19.1971 DULY PASSED BY THE CITY COU	INCIL, AND RULES OF THE
NAME OF CONTRACTOR At to the	in the contract of	and the second s

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.