FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2233

Date Inspected June 26 4h	If so how and location from first manhole down stream
House No. New 1023	Distance from first manhole
Size of pipe used 4 in	down stream to ditch at curb line and depth
Was lateral at curb?	
Was attached to main	Name of Contractor Sunbach
Show by diagram relation of lateral to	wall of building served.
	15%
	3'4 ft Pipe
Rigger 1948 (Lamberg Brown 1944)	
X	more Makinley are
Signed A. T. Boyd	Filed at Engineer's Office JUN 2 8 1976
Inspector for Ci	asted to lateral at- a. I by the from strait
Remarks Jaleral Coms	The received and the said of the

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER No 2233 for which permission is grantedsewer, on the Ave., the premises being Lot. No. 3 3 5 1 70/4

House No. 1023 Work to be done in accordance with Ordinance No. 2323, duly part

by the City Council, and Rules of the Department of Public Service.

Name of Contractor