FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED -2680Date Inspected And 1913 29 If so how and location from first manhole down stream... House No. Modelie Distance from first manhole down stream to ditch at Size of pipe used curb line and depth... Was lateral at curb? 22 200 Was attached to main_____ Show by diagram relation of lateral to wall of building served. and the second of the second s STEELER BAR Connect year of the New Connection run in lateral from curb to main Ok lateral laid invision to be

ICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER Massillon, O. for which permission is grante the premises being Lot. No Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule the Department of Public Service. Name of Contracto NOTE. This permit covers work outside of building only. Any work inside walls of buil is subject to Massillon Board of Health Regulations.