Date Inspected Nov 7	If so how and location from first manhole down stream	ortfall
House No. 22 9 5 10 10 Size of pipe used 6 22	Distance from first manhole down stream to ditch at curb line and depth	
Was lateral at curb? 1488	사용 경우 HT 등 사제를 다양 함께 보고 있습니다.	
Was attached to main. Show by diagram relation of lateral to		
이 사람들이 되지 않는 것이 되었다. 살아지는 물건에서 가장 되고싶다. 그는 다른 그는 그를 가장 하는 것이 그를 가장 하는 것이 없는 것이다. 그는 그를 가장 하는 것이다. 그는 그를 가장 하는 것이다.	1870 x 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
type of Street House No.	78 H Pike	
House No.	178 HOLDE	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N _o	2812		PERM	IIT T	O TAP	SEWI	ER
			d bus yed es	the state of the s		1 / / / / / / / / / / / / / / / / / / /	, T.K. (
		(m) 100 m	ab elodúsm 12 A mari dorego Borrasyotaya	Massillon	(0., <i>(</i>		192 ان ن و
	ceived of permission is	granted		Ñ.	A a a	tee_lot	
to tap	da.	La La	nlay I to see	ver, on the			25 (V
of M	an	211			e of Street	Kar	-c. d
	coln Way ses being Lot.	_	350	St. 4339	Iouse No	22	
			Ordinance N	o. 2323, duly	passed by the	: City Council	, and Rules
리스 글로그스를 간 크로그램 기술당 기	tment of Publi		e.l.				
Name of	Contractor. 2		Carlotte of				Signe

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.