

CTII OI MASSILLOM, OUTO **151 LINCOLN WAY EAST**

MUNICIPAL GOVERNMENT ANNEX

CITY ADMINISTRATION BUILDING **MASSILLON, OHIO 44646** PHONE 330-830-1722 FAX 330-830-1786

PERMIT DATE:

9/18/03

PERMIT NO.

3050

his permit is issued subject of work (220) 920, 1722	t to the latest Codified Ordinances of the City All permits issued under this ordinance are v	of Massillon, OH. The City Engine	SEWEK eer to be notified 24 hours in advance of
RECEIVED OF:	PERMIT		
CONTRACTOR INFORMATION		SITEINFORMATION	
CONTRACTOR:	COUNTRYSIDE EXCAVATING	OWNER'S NAME:	LAUBACHER, KEN
CONTACT:	SCOTT ROWLAND	STREET NUMBER:	2307
ADDRESS:	7333 MILLER STREET	STREET NAME:	AMBERWOOD CR NE
CITY:	APPLECREEK	CITY LOT NUMBER	14729
STATE:	OHIO	PURPOSE OF CUT:	SANITARY
ZIP:	44606-	ZONING CLASS:	
PHONE:	(330) 465-0969	STREET SIDE:	NORTH
FAX:	The state of the s	PHONE OTHER:	A literature in a management of the contract of the literature of
SURETY:	ERIE INSURANCE	NOTE: This permit covers work walls of the building is subject to	outside of the building ONLY. Any work inside the Massillon Board of Health Regulations.
SANITARY SEWER CONNECTION: SKETCH: DRAWING #:			
USAGE: RESIDENTIAL COMMERCIAL INDUSTRIAL			
DATE INSPECTED			# 3050 Ambenwood CR NE
located on the $9 \cdot 23 \cdot 03$ side of		12	Allocation of the
North	between	, <i>V</i>	3 ^{dp} -6'
Amberwood CK NE and			-6'
ementality The Market Control of			·-
Direction from downstream Manhole:			-28'
Distance from downstream Manhole: 86'			
Connection Leng	th: 86 0.00 (FEET)		-46'
Connection Depth	1: 0 (FEET)		
Size of Sewer Pip	e: " (INC	CHES)	d^22°
Pipe Material:	PVC		
INSPECTORS NA	ME: Bill Pappas	SANITARY SEW	ER PERMIT FEE: \$50.00
COMMENTS:	Coes into stub from N	;	กระคาสาขางการเปลี่ยวสาขานการเปลี่ยวสาขานการเปลี่ยวสาขานการเปลี่ยวสาขานการเปลี่ยวสาขานการเปลี่ยวสาขานการเปลี่ยว
	COES MIGO DIO 4, OM PI		TOTAL COST: \$50.00
	NG DAYS BEFORE YOU DIG	week soul	響からからます。coldien add down abusenesses (
Ohio Utilities Protection Service			ECTOR OF PUBLIC SAFETY AND SERVICE
Call 1-800-362-2764 Toll Free Non-Members must be called directly.		ISSUED DT:	LINDA MIKUTEL