	· 00017
in analysis of initiation and an initial	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 3473	AND SIGNED WHEN RETURNED
Date Inspected 7.7.3. House No. 2.2. Size of pipe used 6.2. Was lateral at curb? 7.2. Was attached to main 7.2. Show by diagram relation of lateral attached to main 7.2. All satisfies 1.2. All satisfies 2.2.	I so how and location from first manhole down stream Distance from first manhole down stream to ditch at curb line and depth. Name of Contractor Name of building served.
Signed Land Inspec	Filed at Engineer's Office.
Andrew State Communication (Communication Communication Co	NOTTO A

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

3473 for which permission is granted sewer; on the . House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

the premises being Lot No.

This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.