Nº 4003	AND SIGNED WHEN RETURNED
DATE INSPECTED 10/27/38	IF SO HOW AND LOCATION FROM 775
House No. 7,33	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
Was Lateral at curb? Ves	CURB LINE AND DEPTH
Was ATTACHED TO MAIN Yes	NAME OF CONTRACTOR SET LANGE
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.
TENETE TO STATE	3VA N 30 / 6'6"
Commission of the contract of	\sim 70.00 to 1 of the parameter $^{\prime}$
Dytij est verteras parc erec	Correspondence of the second with Ordinance for
MH A CO	75 7 7 2 2 2 2 2 3 2 2 1 2 2 2 2 2 2 2 2 2 2 2
SIGNED John Ely	FILED AT ENGINEER'S OFFICE 10/27/38

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE N_{\odot}^{0} 4003 PERMIT TO TAP SEWER

######################################		Massillon, Ohio,	
RECEIVED OF	🖴 Soop bay	4	FEE OF \$ 2
FOR WHICH PERMISSION IS G	그: HTS목명(유명선 공원()) 교육되고.	. () [37] : قال نامال المراد الماد المساوية في الطبيعية المراد المراد الماد الماد الماد الماد الماد الماد الم	무면 프랑무 경우 교육적인 등은
and the contract of the contra	医乳球虫科 化二甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	가게 되면 하는 이 가게 가득하게 💼 나는 그 때 그는 그 것이 한 경우를 살았습니다.	
TO TAP 5.77	SEWER	ON THE	
OF TOURTH		こうがき かったい かいこまり マームしょう カイロ はいしゃ かった 日連報 なかしょう	19、19、19、19、19、19、19、19、19、19、19、19、19、1
THE PREMISES BEING LOT NO WORK TO BE DONE IN ACCO			

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.