Kathy Catazaro-Perry, Mayor

CITY OF MASSILLON, OHIO

151 LINCOLN WAY EAST MUNICIPAL GOVERNMENT ANNEX CITY ADMINISTRATION BUILDING **MASSILLON, OHIO 44646** PHONE 330-830-1722 FAX 330-830-1786

PERMIT	DATE:
	3/19/2013
PERMIT I	NO.
Γ	4241

This permit is issued subject to the latest Codified Ordinances of the City of Massillon, OH. The City Engineer to be notified 24 hours in advance of start of work (330) 830-1722. All permits issued under this ordinance are void after 120 days from date of issuance.

RECEIVED OF:			PERMIT TYPE	Rep	air	Marian Manian Marian Marian Marian Marian Manian Marian Marian Marian Ma	
CONTRACTOR INFORMATION		SITE INFORMATION					
CONTRACTOR:	Roto Rooter		OWNER'S NAI	ME:			
CONTACT:			FULL STREET	•	480 Standish	Avo NIV	1
ADDRESS:		one of the same of	ADDRESS:		,	- -	ľ
CITY:			CITY LOT NUM		11014		
STATE:			PURPOSE OF	CUT:	Repair		
ZIP:			ZONING CLASS:				
PHONE:	(330) 456-7890		STREET SIDE:	:			
FAX:							
SURETY:		-	PHONE OTHER	R:			
SANITARY SEV	VER CONNECTION	ON:	NOTE: This permit co- inside walls of the buil	vers work ding is su	outside of the buildir bject to the Massillor	ng ONLY. And Board of He	y work ealth
USE: Residentia	al		SKETCH:		WING #:		
DATE INSPECTED	3/20/2013				,	#4	1241
located on the	AST side	of		1	1		
STANDISH AVE N	IW	between		480	Standish Ave NW		
ALDEN NE		and			⊢ 7'-	See old Per	mit # 5872
STANDISH CIR N	W		←				
Direction from do	wnstream Manhole	: NORTH					
Distance from downstream Manhole: 89		Chan Jinh	curb	3.4p 7	replaced 9' o	f 6" pipe	
Connection Length: 9.00 (FEET)			Standish	Ave NW		89' fr	om DS MH
Connection Depth	1: 3	(FEET)					
Size of Sewer Pipe	e: 6	(INC	HES)	TION			
Pipe Material:	PLASTIC		INSPEC	HON	REQUEST:	l	<u>3/20/13</u>
INSPECTORS NAI	WE: JEFF KING		SANITAR	Y SEV	VER PERMIT	FEE:	\$75.00
COMMENTS:	UTILITY POLE CRUSHED				CAPACITY	FEE:	\$0.00
LATERAL					TOTAL CO	DST:	\$75.00
TWO WORKING DAYS BEFORE YOU DIG		ALITHORIZED BY: DIRECTOR OF PURI IC SAFETY AND SERVICE					

Ohio Utilities Protection Service Call 1-800-362-2764 Toll Free.... Non-Members must be called directly.

ISSUED BY: Linda Mikutel