FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 44. AND SIGNED WHEN RETURNED

DATE INSPECTED 4-//- 4	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2405	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Yes	
WAS ATTACHED TO MAIN 725	
	LATERAL TO WALL OF BUILDING SERVED.
Harsh. Aven	Sult of Landing of the state of
ng propinsi palakan ng manakan ng katalang ng mga manakan sa sa ng palakan ng palakan na sa naggaratan ng palak	
SIGNED John Eh	FILED AT ENGINEER'S OFFICE 4/19/4/1

No

4863

Nº 4863

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Ben Hallon, Ohio, 11
	RECEIVED OF
	FOR WHICH PERMISSION IS GRANTED BOWN WHICH
lue	TO TAP Santay SEWER, ON THE South
	of) land and LAVE., Type of Street hard sufface
	THE PREMISES BEING LOT NO. 07 02314, House No. 2405
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR REMIE

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.