Nº 5042

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-11-47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 12/9		\
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	-
WAS LATERAL AT CURB? 155	-	
` 4 💉	NAME OF CONTRACTOR Diana	2.7.5
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	
OAK Ave	5.E. 6'deep 53 7'd.	e af
SIGNED John Eliz	FILED AT ENGINEER'S OFFICE	40/2/7
INSPECTOR FOR CI	TY TY	strojenskip u opera samunu. B
REMARKS:		

Nº 5042

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			~	
ė i			10/	
		Massillon, Ohio,	17/7	7
	\bigcirc			194 <u>.F_</u>
الاستان	RECEIVED OF	1. Oraphin	, , , , , 2	
ĬL	FOR WHICH PERMISSION IS GRANTED	14.7	udin.	
	TO TAP Santan	ER, ON THE	Ann H	
	or Oak and &	YPE OF STREET	orlea	SIDI
7	THE PREMISES BEING LOT NO. OT OX	5 9 House No.	1219	
		the same of the same		
:	WORK TO BE DONE IN ACCORDANCE WITH ORDINAN	ICE NO. 2323. DULY PAS	SED BY THE CITY COU	NCIL. AND
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		and the second section of the second section is a second section of the section of the second section of the section of the second section of the second section of the second section of the section of	
·W		*		
	NAME OF CONTRACTOR	and		,

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.