## .

5145

 $N_0$ 

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-14-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 810 Rear.	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR STable Ker.		
SHOW BY DIAGRAM RELATION OF LATE	TALLO WALL OF DOILDING SERVED.		
NORTH Ave	NE. steen out 12 rice fix S		
K			
	6'deeft = 11-		
	THE ST. NE.		
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 4-28-48		
REMARKS: Connected to lateral from house in allega			

## Nº 5145

## PERMIT TO TAP SEWER

	Massillon, C	оню, 6/10	1940
RECEIVED OF Ato -	Rootenseu	ver Ol Che of	\$ 200
FOR WHICH PERMISSION IS GRANTED		A Comment of the Comm	
OTAP LAN	sewer, on the	70.	SIDE
, Thurth DE	AVE TYPE OF STREET_	Para le	· · · · ·
HE PREMISES BEING LOT NO.	2 /	JSE NO. 8/0.	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR KAte - Ranter Sewen Co.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.