

9-3

Nº 5231

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-15-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM68'6 1/2" deep.HOUSE NO. 3081SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

Lincoln Way. N.W.

SIGNED

John E. Lerner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1-5-49

REMARKS: _____

Nº 5231

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/6 1948

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Trinity Lutheran Ch.

TO TAP San

SEWER, ON THE S

SIDE

OF Lincoln Way NW

AVENUE TYPE OF STREET Paved

ST.

THE PREMISES BEING LOT NO. 4216

HOUSE NO. 3081

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.