Nº 5233

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED / -3-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE BOSHEL STREAM	2 dec/s
HOUSE NO	Op.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DEATH STREAM TO DITCH AT CURB LINE AND DEPTH	1-6" beef
WAS LATERAL AT CURB?	4 /	
WAS ATTACHED TO MAIN		77 8.
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
10th ST	N.E.	
		¥
*************************************	N	- 1
	Market Service Co.	
		6 E 2'dads
11 91		
SIGNED FILED AT ENGINEER'S OFFICE 1 = 49		
REMARKS: Relaid fr	om main to curt	2,

Relay
Nº 523

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

43 .9
Massillon, Ohio, 194
RECEIVED OF THE OF STATE OF ST
FOR WHICH PERMISSION IS GRANTED AND HORNALL
TO TAPSEWER, ON THESIDE
OF 10 Th D & AVE. TYPE OF STREET CILL
THE PREMISES BEING LOT NO. 759 4 HOUSE NO. 884
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Celams.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.