Nº 5283

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-6-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1019	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7 deef
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR ASTOM	
SHOW BY DIAGRAM RELATION OF LATE 4 TH ST. SIM	RAL TO WALL OF BUILDING SERVED.	4/4
<u> </u>	186	7. Lief 3
SIGNED John English INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE_	6-16-49

Nº 5283

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		4/2	~	~
	Massillon, Ohio,		1947	1
RECEIVED OF Ja Cotyn		FEE OF	82 000/	
FOR WHICH PERMISSION IS GRANTED	con al	mel		
TO TAP LUND SEWE	R, ON THE	ki in in in	g	IDE
OF A+O D W AVE.: TY		les		
THE PREMISES BEING LOT NO. 4/1/2.	de la companya de la	1019		
Work to be done in accordance with Ordinano Rules of the Department of Public Service.	CE NO. 2323, DULY PA	SSED BY THE CIT	ry Council,	IND
NAME OF CONTRACTOR (Later)				

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.