

Nº 5639

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-15-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1704

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

89'

5' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN VCS

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Windsor Rd. N.E.

N

6' deep

18

3

5' deep 89'

SIGNED

John Ehrmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-18-51

REMARKS:

NO 5639

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/14 1916

RECEIVED OF C. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Jacob H. Glick

TO TAP San

SEWER, ON THE E

OF Windsor

AVE.

TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 8491

HOUSE NO. 1704

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.