N9 6063

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO
SIZE OF PIPE USED 6" OPENING STREAM TO DITCH AT 50 8 Deep
WAS LATERAL AT CURB? YCS
WAS ATTACHED TO MAIN NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
4 2 Deep
8 Deep S Approx S. Curb Line
& Sewer in Bradfords /k 50's
SIGNED R.J. Angle FILED AT ENGINEER'S OFFICE S/1/2
INSPECTOR FOR CITY
REMARKS:

11-21

Nº 6063

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO. 6/9/53
	RECEIVED OF 1 1 ana FEE OF 5 2
0	FOR WHICH PERMISSION IS GRANTED DA R Resholds
	TO TAP Danilary SEWER, ON THE South
	of Bradford Ranker Type of STREET Dilea
	THE PREMISES BEING LOT NO. 1/133 , HOUSE NO. 1/37

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.