Nº 7387

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3		IF SO HOW AND LOCATION FI FIRST MANHOLE DOWN STRE		8 De	0,0
HOUSE NO. /20	6"	DISTANCE FROM FIRST MANH DOWN STREAM TO DITCH AT	OLE.		·.
WAS LATERAL AT CURB?	NO	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN		NAME OF CONTRACTOR		Execuar	ling
		de la companya de la La companya de la companya de		1 7 dup	
	A. (10.1.1)		9/2011/2		
		Maria da didagirka da M			
D 1	1-1		O '8'		
SIGNED / INSP	ECTOR FOR CITY	FILED AT	FENGINEER'S OFFICE	2-6-62	
REMARKS	· · · · · · · · · · · · · · · · · · ·				

5-22-47 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

1987 No. 7387

THE SEWER OF PERMIT TO TAP SEWER

•		
	Massillon,	OHIO, 5/3 19
not	RECEIVED OF THE AMERICAN ASSESSMENT ASSESSME	
	FOR WHICH PERMISSION IS GRANTED / 100	
	TO TAPSEWER ON THE	<u> (i)</u>
	OFST. TYPE OF STREET.	mark i
	THE PREMISES BEING LOT NO. 5/14/	HOUSE NO. 1309
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 232	3, DULY PASSED BY THE CITY COUNCIL
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
تساس	NAME OF CONTRACTOR BOARD Ffrence	ting

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.