Nº 7806

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-8-25	IF SO HOW AND LOCATION FROM IN MH @ 2357	
HOUSE NO. 23/0	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO		
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
, the control of		
and the second great with the second second great for		
	a_{D}^{\prime}	
SIGNED PI WELLEN	FILED AT ENGINEER'S OFFICE	
PEMARKS	for the more appropriate that the following the form	

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

Nº 7806

13,1965	MASSILLON, OHIO, Sunt 3
10 Anderna	RECEIVED OF FEE OF \$5
10 (Vary 8.	FOR WHICH PERMISSION IS GRANTED (1.7) Troda ama
Cart Sela	TO TAB SEWER ON THE York
A	ofene Way E. AVE. TYPE OF STREET Blow Dist
0 + 1417	10.1.330 +0.4.417 , HOUSE NO. 23/0
310	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AI
2. L. Marks	of the Department of Public Service. A. Marks

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

o Innacesa