Nº 8402 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-1-7/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 150' SOUTHOF HONFORD, 11'D CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES	NAME OF CONTRACTOR HUMBERT BOOS, INC.
WAS ATTACHED TO MAIN	
SHOW BY DIAGRAM RELATION OF LATE	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	To all of the could
Welliam &	6 150 511'D

REMARKS

Nº 8402

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO HANGELLE 39
RECEIVED OF Himbert Biss	Inc. FEE OF 9.75.
FOR WHICH PERMISSION IS GRANTED Parallel	Ice
TO TAP Sanutary SEWE	BONTHE South
of livane and. 71. W. AVE. TYPE	OF STREET Chip & Side
THE PREMISES BEING LOT NO. 1343741/1/134	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Humbut Bend, Que.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.