Nº	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED				
ate Insp	ected <i>OC1</i> -22	If so how and locat			
	New 858	first manhole down Distance from first down stream to dite	manhole ch at		

Size of pipe used 4

Was lateral at curb? 1908 Was attached to main

Name of Contractor M & Lumba

Show by diagram relation of lateral to wall of building served.

Filed at Engineer's Office 0CT 2 5 1926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2292 PERMIT TO TAP SEWER

Massillon, O., Quantity of 19	<u>021</u>
Received of fee of \$ 2	ELP.
the state of the s	
to tapsewer, on the	side
of Ave., the premises being Lot. No St.	<u>C</u>
House No. Work to be done in accordance with Ordinance No. 2323, duly p	assed
by the City Council, and Rules of the Department of Public Service.	