FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2367

Date Inspected OCA	If so how and location from first manhole down stream
House No. 220	Distance from first manhole
Size of pipe used	down stream to ditch at
Was lateral at curb?	Name of Contractor dess. Bunker
Was attached to main	
Show by diagram relat	n of lateral to wall of building served.
	1 1 2 1 - P: 1 2 1
	3 / 20 Pro Paper
	South & main Sever
A Dr. D	West-Oak 21-
Signed A. J. B.	Filed at Engineer's Office OCT 1 4 1926
Remarks Later	I connected to lateral at curt 25 ft from ob
	D. A. Harris

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2367 PERMIT TO TAP SEWER Massillon, O., Get 12th

Received of	Bel M.	Michal	fee of \$	00
www.		13	See -	
for which permission is	granted	47 / 370		
to tap Aavu	kany se	wer, on the	boot	side
of Musk	engun	the premis	es being Lot. No.	
		St.		

House No. 2223, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Jess / grunker