FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 2450 If so how and location from first manhole down stream. Distance from first manhole down stream to ditch at down stream to ditch at Colors 8-1 Size of pipe used Was lateral at curb? Name of Contractor Was attached to main______ Show by diagram relation of lateral to wall of building served. Lingia in sevi . syl. Filed at Engineer's Office DEC 2 2 1926

Nº 2450

PERMIT TO TAP SEWER

| so how and located from | i Almongo Alexandra |
|--|--|
| Received of Leading the property of the Received of Leading to the leading to the leading the state of the leading the | Massillon, O., <u>A. C.</u> 192 |
| for which permission is granted. Mich | Contract fee of 82 |
| to tap Canada Set Set Control | wer, on the |
| of | 4、克勒·马克·克克·克克·克克·克克·克克·克克·克克·克克·克克·克克·克克·克克· |
| | o. 2323, duly passed by the City Council, and Rule |
| the Department of Public Service. | |
| Name of Contractor/ Walter and American | |

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.