FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 2590 AND SIGNED WHEN RETURNED Date Inspected May 2 If so how and location from first manhole down stream... Distance from first manhole down stream to ditch at Size of pipe used b. curb line and depth... Was lateral at curb? Was attached to main\_\_\_\_ Show by diagram relation of lateral to wall of building served. Ave., Type of bereet 2/since with Ordinance No. 2323, duly passed by the Oby Council, and Kules of

Remarks Lateral Connected to lateral at curt 15 ft from estrail

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 $N_{\bullet}^{o}$  2590

## PERMIT TO TAP SEWER

|          | ment nonegot one work on it  |
|----------|--|
| J. A.    | Received of fee of 8 c2  |
|          | for which permission is granted.   |
| J-\$\s\- | to tap sewer, on the sewer of the sewer of the sever of the sewer of t |
|          | the premises being Lot. No. House No. 28  Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule   |
|          | the Department of Public Service.  Name of Contractor  |
|          | NOTE. This permit covers work outside of building only. Any work inside walls of builts subject to Massillon Board of Health Regulations.  |