

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

1-5

No. 3479

Date Inspected July 23

I so how and location from
first manhole down stream

House No.

Distance from first manhole
down stream to ditch at

Size of pipe used

curb line and depth

Was lateral at curb?

Was attached to main

Name of Contractor

Show by diagram relation of lateral to wall of building served.

Ice Cream

Connected to old line

Signed

Inspector for City

Sin way East
Filed at Engineer's Office

AUG 14

Remarks:

this was inspected by plumbing Inspector Burner Co
iron pipe Hostetter not responsible

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3479

PERMIT TO TAP SEWER

Massillon, O.,

Apr. 22

1921

Received of

Palmer, B. B.

for fee of \$ 2.00

for which permission is granted

Chas. E. Hostetter

to tap

Sanitary

sewer, on the

North

of

Lin May E.

Ave., Type of Street

paved

the premises being Lot No.

Pl. 127

497

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor

Hostetter

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.