FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 4545 AND SIGNED WHEN RETURNED FIRST MANHOLE DOWN STREAM HOUSE NO. DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB?_ WAS ATTACHED TO MAIN VCS SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED 3 tH 57 NIN REMARKS

Nº 4545

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			n jakin dalam Masar dalam	ale de la ver	or sole year 200		6/2	
ر تابع المستقولية - الماج المستقولية			ii wasini e		MAS	ssillon, Ohio,	<u> </u>	1
A .	R	ECEIVED OF	\mathcal{A}	cery verse	1/200	-a		FEE OF \$
Ada Juliani	ديوند الله المعالمية المحالة المعالمية			V /	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		in ch	
	FOR WH	IICH PERMI	ssion is GRA	ANTED Z			aup. T.A.JA:	
	TO TAP_	00	initi	T-ry	SEWER, ON	THE 1	مربار	4-7
				1.0	orusarar Lighter	30.807/	May 2	· Frila
	OF				VE., TYPE OF	STREET		
	THE PRE	MISES BEIN	G LOT NO	207	?	, House N	<u>, / (</u>) 33

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DU RULES OF THE DEPARTMENT OF PUBLIC SERVICE,

AME OF CONTRACTOR W // LAnd

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.