

Nº 5209

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14-27

DATE INSPECTED 10-12-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 338'

11' deep

HOUSE NO. _____

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Brookside Acres.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-30-48

REMARKS: _____

Nº 5209

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/14 1944

RECEIVED OF

Raymond Remley

FEE OF

5.00

FOR WHICH PERMISSION IS GRANTED

Ray Brown

TO TAP

San

SEWER, ON THE

N.

SIDE

OF

Brookside Ave.

AVE.
ST.

TYPE OF STREET

THE PREMISES BEING LOT NO.

25

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.