Nº 5838

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8- 6-5-2	IF SO HOW AND LOCATION FROM
HOUSE NO. 482	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? // 0	and the first production of the second section of the sect
WAS ATTACHED TO MAIN YPS	NAME OF CONTRACTOR LA 1600 Cht
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	3 - 1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2
	1 N Q decp
rapida and the second of the property of the second	e de la completa del completa de la completa de la completa del completa de la completa del la completa del la completa de la completa del la completa de la completa del la comple
•	events design the decrease expension of the restriction of the second
	Mainsewer 7/8'dup
	Carulana 7/8 olup
	5-7'
SIGNED LEVOY Baths	FILED AT ENGINEER'S OFFICE 8-18-53
/ INSPECTOR FOR CI	TY
REMARKS:	en de la composition de la composition de la grandation de la composition de la composition de la composition La composition de la

Nº 5838

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		بوكار وساند المعادية الأنج سنساء	MASSILLO	3.9 1	July 30	1:
F	RECEIVED OF GAR	an Paige Co	estreet	ion Com.	FEE OF S	8.
FOR WH	ICH PERMISSION IS GRAN	ited Same			977 L. 2. 3. 3. 736 L. 24 L.	
то тар_	Sanitary	SEWE	R. ON THE	Bast		
OF	Carver NW	AVE., TY!			1 75	
THE PRE	MISES BEING LOT NO	10997		HOUSE NO.	482	
Work T	O BE DONE IN ACCORDA					~~
	F THE DEPARTMENT OF F	·		S, DULY PASSE	D BT THE CITY C	JOUNG

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.