FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6234 AND SIGNED WHEN RETURNED.

	F SO HOW AND LOCATION FROM Garage Attached to hou IRST MANHOLE DOWN STREAM
HOUSE NO. 2750	
SIZE OF PIPE LIGED 9"	ISTANCE FROM FIRST MANHOLE OWN STREAM TO DITCH AT URB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN YPS	IAME OF CONTRACTOR Wolfer Wentery
SHOW BY DIAGRAM RELATION OF LATERAL	L TO WALL OF BUILDING SERVED.
	2 2 del 0 -4-1 House
	on L.W. W.
	it is in the chilific to the second party of the second section of the second section is the second section of
SIGNED INSECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS:	uli perdiki padawiji komak polisi iyo ili ingila di kanila ing

Nº 6234

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Massillon, Ohio, 78
RECEIVED OF Remover FEE OF \$ 20
Head of the
FOR WHICH PERMISSION IS GRANTED VINCELLA ON
of Jeneal Way have Type of Street Paned.
THE PREMISES BEING LOT NO. 989 , HOUSE NO. 2850
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.