NO 7317 AND SIGNED WHEN RETURNED

	5 W. OT 177
DATE INSPECTED	IF SO HOW AND LOCATION FROM TAPPED BYOOK SI-14TY UNK
HOUSE NO. 2209	
SIZE OF PIPE USED	DISTANCE-FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY 10	<u>an makasan kangatan di merupakan di kantan di kantan di merupakan di kantan di kantan di kantan di kantan di k</u>
WAS ATTACHED TO MAIN 7.05	NAME OF CONTRACTOR Joe & Jan
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	18
The second secon	
and the state of the second state of the sta	vista eta talia di ancia di ancia di antica di
, seemandelle	and the state of t
N. C.	0-55 1 Jupped will
63 -6-1-12	540 DL & 45° BEND
SIGNED IN A STATE OF THE	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	Trefficents of subject to place to place 7-6-67

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, aug 27 19
RECEIVED OF 19 & RIGHTS FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED Same
TO TAP SAW SEWER ON THE South
OF May Nouth 7W AVE. TYPE OF STREET Hard Surface
THE PREMISES BEING LOT NO. 12/24 , HOUSE NO. 2209
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR // Y // Y
Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.