

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB?_____

NAME OF CONTRACTOR WEAVER & SON

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Henlock



SIGNED William J. Hays
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8864

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Oct. 6*

RECEIVED OF

David Gardner

FEE OF \$

2.50

FOR WHICH PERMISSION IS GRANTED

Mark Weaver & Sons

TO TAP

Sanitary

SEWER ON THE

North

OF

Floyd C. H.W.

AVE.
ST.

TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

983

, HOUSE NO.

2908

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Mark Weaver & Sons Inc.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.