## **Nº** 9230

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Oct 18 28	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? Taff in Mit	Beaner	·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	LE OF BOILDING SERVED.	•
	Lank	
	Denston MH	
. · · · · · · · · · · · · · · · · · · ·	Denistan MH 20 feet	
0	Erlinrosal	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE	

**Nº** 9230

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Oct. 10		
RECEIVED OF Out Ida Lands	FEE OF \$50 U		
FOR WHICH PERMISSION IS GRANTED Out Date Fands			
TO TAP Sanctary SEW	ER ON THE Sauth		
of Churchin Ad. S.V. AVE. ST. TYP	FIF STREET Hand Lunface		
THE PREMISES BEING LOT NO. $Oh 1971$	60		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.