FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 2425 SIZE OF PIPE USED 6 WAS LATERAL AT CURB?	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
SIGNED Bilo Page	10'4 5'AGS 23'K 120'2' 9'DEFF 45' FILED AT ENGINEER'S OFFICE	
Inspector for City	·	

Nº 11071

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio, May 22, 20_	
RECEIVED OF Malavite	FEE OF \$5	
FOR WHICH PERMISSION IS GRANTED	slav, te	
TO TAP SEWE	RONTHE West	
OF UNIVERSITY DE SAVE.		
THE PREMISES BEING LOT NO		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR Malavite		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.