

## CITY OF MASSILLON, OHIO

151 LINCOLN WAY EAST
MUNICIPAL GOVERNMENT ANNEX
CITY ADMINISTRATION BUILDING
MASSILLON, OHIO 44646
PHONE 330-830-1722 FAX 330-830-1786

PERMIT DATE	PE	RMI	ΓD/	ATE
-------------	----	-----	-----	-----

11/25/2003

PERMIT NO.

3108

## PERMIT TO TAP SANITARY SEWER

This permit is issued subject to the latest Codified Ordinances of the City of Massillon, OH. The City Engineer to be notified 24 hours in advance of start of work (330) 830-1722. All permits issued under this ordinance are void after 120 days from date of issuance.

RECEIVED OF: PERMIT TYPE: V NEW REPAIR CUTOFF						
CONTRACTORIN	EORMATION	SITE INFORMATION	SITE INFORMATION			
CONTRACTOR:	BEAVER EXCAVATING	OWNER'S NAME:	MASSILLON MIDDLE SCHO			
CONTACT:	MATT WOODS	STREET NUMBER:	250			
ADDRESS:		STREET NAME:	29TH ST N			
CITY:		CITY LOT NUMBER	OL 0504			
STATE:		PURPOSE OF CUT:	TAP SANITARY MANHOLE			
ZIP:		<b>ZONING CLASS:</b>	R-1			
PHONE:	(330) 478-2151	STREET SIDE:	EAST			
FAX:		PHONE OTHER:	A MANAGEMENT OF THE PARTY OF TH			
SURETY:	man more many the same annual annual annual services of the same annual annual services of the same annual service	NOTE: This permit covers work	toutside of the building ONLY. Any work inside to the Massillon Board of Health Regulations.			
SANITARY SEWER CONNECTION: SKETCH: DRAWING #:						
USAGE: O RESIDENTIAL O COMMERCIAL O INDUSTRIAL						
DATE INSPECTED						
located on the side of						
between						
and						
Direction from do	wnstream Manhole:	- x				
Distance from dov	vnstream Manhole:					
Connection Length: 0.00 (FEET)						
Connection Depth: 0 (FEET)						
Size of Sewer Pipe	e: (INC	HES)	FOURT T			
Pipe Material:		INSPECTION RI	EQUEST:			
INSPECTORS NAME:		SANITARY SEWI	ER PERMIT FEE: \$50.00			
COMMENTS:	TAP #1, JUST SOUTH OF 29T	and the same of th	J · · · · · · · · · · · · · · · · · · ·			
	STANTON INTERSECTION	•	TOTAL COST: \$50.00			
TWO WORKING DAYS BEFORE YOU DIG		er en suit	# ****			
	ities Protection Service	<u></u>	ECTOR OF PUBLIC SAFETY AND SERVICE			
	0-362-2764 Toll Free ers must be called directly.	ISSUED BY:	IASON HAINES			