

MASSILLON DAILY INSPECTION REPORT

REPORT NO.

Date: 6/15/2010

Project: Oxford Storm Road: Oxford

Weather: AM: SUNNY Temperature: AM: Precipitation: none
PM: SUNNY PM:Lost Day: Yes ☐ No ☐ Reason:

Contractor: Wenger Excavating

Foreman: Chris

Employee: 3

Sub-Contractor:	Foreman:	Employee:
Sub-Contractor:	Foreman:	Employee:
Sub-Contractor:	Foreman:	Employee:

Electric: ☐ Contact: Reason:
Gas: ☐ Contact: Reason:
Water: ☐ Contact: Reason:
Cable: ☐ Contact: Reason:
Phone: ☐ Contact: Reason:

Equipment:

Dump Truck: 3 Paver: Grinder Tack: Roller: 2 Rubber Tire Roller:
Back-Hoe: 1 Skid Steer: Loader: Track-Hoe: 2 Tandom: Compacter:
Dozer: Pan: Water Truck: Curb Machine: Concrete Truck:

Paid Item or Ref No.	Plan Page	Location or Description	Quantity
304		Granular Backfill	
603		15" Pipe with two collars	92
		Mobilization, Sawcut Pavement	1

Notes:

Attachments: Yes ☐ No ☐

Inspector: FREDERICK WERNER

