

MASSILLON DAILY INSPECTION REPORT

REPORT NO. 1

Project: Wooster Trunk Plug Road: 50' South of 700 Wooster Trunk Sanitary Date: 8/2/2011
 Weather: AM: SUNNY Temperature: AM: 81 Precipitation: None
 NOON: _____ NOON: _____
 PM: _____ PM: _____
 Lost Day: Yes ☐ No ☐ Reason: _____


Contractor:	Holderbaum	Foreman:	Gary	Employee:	2
Sub-Contractor:		Foreman:		Employee:	
Sub-Contractor:		Foreman:		Employee:	
Sub-Contractor:		Foreman:		Employee:	
Sub-Contractor:		Foreman:		Employee:	

Equipment:

Back-Hoe: 1 Loader: _____ Roller: _____ Pavement Grinder: _____ Dump Truck: 1
 Track-Hoe: _____ Compacter: _____ Paver: _____ Tandem: _____ Skid Steer: _____
 Curb Machine: _____ Concrete Truck: _____ Dozer: _____ Pan: _____ Water: _____ Tack: _____

Paid Item or Ref No.	Plan Page	Location or Description	Quantity
Spec		cruch and concrete plug 50' South of 700 Wooster Trunk Sanitary	Lump Sum

Notes:

Attachments: Yes ☐ No ☐Inspector: Frederick P. Werner