## Nº 10036

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

\_\_ 64' from MH to wye \_\_ 31' wye to start of inspection

DATE INSPECTED 7-26-90	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
House No. 2557	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?1/65	
WAS ATTACHED TO MAIN_1/es	NAME OF CONTRACTOR Malavite
Meadowe	wind NE
	N
Theef I	JOARAS 7' cleep @ House
223° 1	Connected 18" from founds  "ELBOW W/ Furneo Fitting
*AA	2-4'x6" clay 20-4'x6" 2 more 4'x6" clay Clay file 450 FL800 16-4'x6" clay
	20 - 11 m 2 more 41 x 6 " 10 m
	Clay tile) 45° FLBOW

Inspector for City

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 10036

MASSILLON, OHIO, 1970
RECEIVED OF MALANITE FEE OF \$ 25.00
FOR WHICH PERMISSION IS GRANTED LOLDICE
TO TAPSEWER ON THESIDE
SEWER ON THE SIDE OF STREET.
THE PREMISES BEING LOT NO. 14010 HOUSE NO. 2557
WORK TO BE DONE IN ACCORDANCE WITH SECTION 29 OF THE CODIFIED ORDINANCES OF THE CITY OF MASSILLON.
NO. OF UNITSOWNERNAME OF CONTRACTOR
NAME OF CONTRACTOR 11 July 12 1

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.