

N^o 10072

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-12-91

IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~TO~~ STREAM

46'

HOUSE NO. 1857

4P

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Just Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

tap

Nº 10072

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 7*

RECEIVED OF *Libert Etc*

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *San*

SEWER ON THE *South*

OF *Vermont Ave SE*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *62383*

HOUSE NO. *1857*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Libert Etc* *open* *1 unit*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**