## Nº 10078

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-18-9/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 425	
WAS ATTACHED TO MAIN 18-5	NAME OF CONTRACTOR 9. lists
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	TO 28 B PEEP  24.
SIGNED BILL TANKS Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS MAIN ON NO	rth side of road

TAP

Nº 10078

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, MICCA	
RECEIVED OF FEE OF \$ 50	
FOR WHICH PERMISSION IS GRANTED LOANL	
TO TAPSEWER ON THE	
OF	
THE PREMISES BEING LOT NO.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.