Nº 10099

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-30-9/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1729	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	. 1
was attached to main $\frac{\sqrt{25}}{2}$	NAME OF CONTRACTOR Lieb
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	14'6"CAST ITON 6'DEEP N 9'DEEP
SIGNED Bill Panasa	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 10099

## OFFICE OF THE DIRECTOR OF PUBLIC SE

MASSILLON, OHIO, May 281
RECEIVED OF JUCK
FOR WHICH PERMISSION IS GRANTED WAS A
TO TAPSEWER ON THE
OF Obuly Pa SV ST. TYPE OF STREET asplat
THE PREMISES BEING LOT NO. 129-16, HOUSE NO. 1729
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.