

Nº 10100

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-6-91

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

92'

HOUSE NO. 1407

SIZE OF PIPE USED —

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Cathell Lumber

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

CURB w/out S.E.



NA

SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 10100
CUT OFF

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 6 1971*

RECEIVED OF

FIVE DOLLARS

00

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Dan CONTRILL

TO TAP

Sanitary

SEWER ON THE

South

OF

Walton

20 SE

AVE.

ST. TYPE OF STREET

Asph

THE PREMISES BEING LOT NO.

3346

HOUSE NO.

1407

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

CONTRILL

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**