Nº 10119

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-29-91	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
NOUSE NO. 44-59 SIZE OF PIPE USED WAS LATERAL AT CURB? 4ES	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN 765	NAME OF CONTRACTOR Cottrell Luden L OF BUILDING SERVED. CURB DIAMING Ct. S.W.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	Curs Diamend Ct. S.W.	5 ¹¹¹
gu	D Z NA	
5 6 8 9	8 4 65	
SIGNED BULL CAME Inspector for City	FILED AT ENGINEER'S OFFICE	. 4
	and Ct. 5W. Could be Tied in under house	flor

(UT off Nº 10119

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	
RECEIVED OF	Mussilla	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
TO JAK 647 - 044	SEWER ON THE	
OF		
THE PREMISES BEING LOT NO. F.	, House No	44, 46, 48, 53
WORK TO BE DONE IN ACCORDANCE WITH O OF THE DEPARTMENT OF PUBLIC SERVICE.	RDINANCE NO. 19-1971 DULY PASSED B	Y THE CITY COUNCIL, AND
Co 41 11		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.