## $N^{0}$ 10132

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

FIRST	HOW AND LOCATION FROM MANHOLE DOWN STREAM	
HOUSE NO. 66/		
SIZE OF PIPE USEDDOWN	NCE FROM FIRST MANHOLE STREAM TO DITCH AT LINE AND DEPTHL	
WAS LATERAL AT CURB? YES		
WAS ATTACHED TO MAIN 1/E NAME	OF CONTRACTOR Buckeye Wrecking	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
7'DEEP	CURG	
SIGNED Bill Passes	FILED AT ENGINEER'S OFFICE	
REMARKS	***************************************	

Nº 10132 OI

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

м	ASSILLON, OHIO, A. J. 18	
RECEIVED OF Lander Comments	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED		
TO TAPSEWE	R ON THE	
AVE, OF ST. TYPE	CF STREET	
THE PREMISES BEING LOT NO	, House No	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	· K	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.