Nº 10139

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-91	IF SO HOW AND LOCATION FROM 292
HOUSE NO. 2600	THE MAINEL BOTH CHARLES TO THE STATE OF THE
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN_4ES	NAME OF CONTRACTOR Diana & Sons
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
1-30° 100	2-30° BENDS 3' DEEP 1-22° BEND
SIGNED Bill Panaes	FILED AT ENGINEER'S OFFICE
Inspector for City	
DEMARKS	

tup

SE
Á
AND
_

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.