

N<sup>o</sup> 10141

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-28-91

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM 106'

HOUSE NO. 1516

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Plus Epc

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N4

SIGNED Bill Pappas Inspector for City

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

*top*  
Nº 10141

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, *Oct 9,*

RECEIVED OF *Belville Apartments*

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *down*

TO TAP *Sanitary*

SEWER ON THE *East*

OF *Morgan Ave*

AVE.  
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *14456*

HOUSE NO. *1516*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Malcolm E. E. Belville Apts*

*1 unit*

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**