

N^o 10142

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-24-91

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES INTO MH.

HOUSE NO. 1913-1921

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Plus Epc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10142

TOP
OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Oct 9*

RECEIVED OF *Le Velle Apartments*

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *Yes*

TO TAP *water*

SEWER ON THE *S*

OF *Langston Ave NE*

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *14527*

HOUSE NO. *1913-192*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Maintenance Etc*

DeVillle Aptc
5 units

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**