Nº 10166

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2620		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN 45.5	NAME OF CONTRACTOR Malavite Epe.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
$S\acute{c}ns \rightarrow 1$	9'6"DEEP	
300 1/	3-2- x 45°	
SIGNED Bill Posters	16' DEEP	
SIGNED / Inspector for City	FILED AT ENGINEER'S OFFICE	
	•	

-100

Nº 10166

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	Das10
RECEIVED OF 1	<u> </u>	FEE OF \$_5_
OR WHICH PERMISSION IS GRANTED	,	
o TAP San, se	WER ON THE	<u></u>
OTAP SAM, SE OF FAMEN OAK UP AVE. TO	PE OF STREET	
HE PREMISES BEING LOT NO	HOUSE N	o <i>2.62.6</i>
YORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N OF THE DEPARTMENT OF PUBLIC SERVICE.	O. 19-1971 DULY PASS	SPEC Lone
NAME OF CONTRACTOR ME A MANAGEMENT AND A		1 unit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.